



PLAN MAP LEGEND

	PROPOSED	COMPLETED
CATFISH SPAWNING BOX	○	●
STAKE TREE	+	+
TURTLE BASKING PLATFORM	⊕	⊕
VERTICAL PLANK STRUCTURE	⊥	⊥
BLACK BASS NESTING STRUCTURE	□	□
FELLED SHORELINE TREE	⊠	⊠
PORCUPINE CRIB	⊞	⊞
PORCUPINE CRIB JUNIOR	⊟	⊟
SHORT VERTICAL PLANK STRUCTURE	⊡	⊡
ROCK RUBBLE HUMPS	⊢	⊢
CONIFER STRING	⊣	⊣
POST CLUSTER	⊤	⊤
POST CLUSTERS PLUS	⊥	⊥
SPIDER HUMPS	⊦	⊦
ROCK STAR STRUCTURES	⊧	⊧
POST STUMPS	⊨	⊨
STONE FRAMED DEFLECTOR	⊩	⊩
SAW-TOOTHED DEFLECTOR	⊪	⊪
ROOT WADLOG DEFLECTOR	⊫	⊫
TIRE STRUCTURE	⊬	⊬
ROAD BED	⊭	⊭

Warning
 East Branch Clarion River Lake is currently drawn down 20' below normal summer pool.
 Habitat structure depths are listed at normal summer pool elevation (without drawdown).

FISH HABITAT IMPROVEMENT PLAN
 for
EAST BRANCH CLARION LAKE, ELK COUNTY
 by
PA FISH AND BOAT COMMISSION
DIVISION OF HABITAT MANAGEMENT

Drawn By: B.S.P., P.E.T. Habitat Manager: Dave Houser Date: 8/11/06

NOT TO SCALE
 FIT IN FIELD
 ALL SIZES APPROXIMATE



NOTE : Blue Text Indicates Proposed Sites
 Black Text Indicates Completed Sites