

# East Branch Sugar Ck Venango County



Before Photos 2008

# 1 Year Later



Note\* 60 foot tree found a home next to our crib

# 2 Years Later



Look how well the bank grew in.

# Before



# 2 Years Later



# Before



# After



1 Year Later



2 Years Later

- We saw about 20 stocked trout holding over on these devices on June 30<sup>th</sup> 2010 when this was last inspected. Before devices were built, anglers said the trout didn't last more than a month from opening day.